



## JOSEPH R. THEROUX

~ CERTIFIED FORESTER/ SOIL SCIENTIST ~  
PHONE 860-428-7992 ~ FAX 860-376-6842  
426 SHETUCKET TURNPIKE, VOLUNTOWN, CT. 06384  
FORESTRY SERVICES ~ ENVIRONMENTAL IMPACT ASSESSMENTS  
WETLAND DELINEATIONS AND PERMITTING ~ E&S/SITE MONITORING  
WETLAND FUNCTION AND VALUE ASSESSMENTS

1/5/24

KILLINGLY ENGINEERING ASSOCIATES  
P.O. BOX 421  
DAYVILLE, CT. 06241

RE: WETLAND DELINEATION, 476 BAILEY HILL ROAD, KILLINGLY, CT.

DEAR MR. THIBEAULT,

AT YOUR REQUEST I HAVE RE-INSPECTED THE PONDED AREA ON THE SUBJECT PROPERTY ADJACENT TO BAILEY HILL ROAD.

IN SEPTEMBER 2016 I INSPECTED THIS GENERAL AREA AND FOUND NO EVIDENCE OF A WATERCOURSE OR HYDRIC SOIL CONDITIONS IN THIS AREA.

ON 12/15/2023, I INSPECTED THE AREA IN QUESTION AND FOUND NO EVIDENCE OF HYDRIC SOILS, AGAIN. NO LOW CHROMA COLORS WERE FOUND, ONLY 10 YR/6/6 HIGH CHROMA COLORS WERE NOTED AT A DEPTH OF 20+ INCHES.

IT SHOULD BE NOTED THAT DUE TO THE HIGH SEASONAL WATER TABLES, LOW SOIL PERMEABILITY AND THE SEVERAL SIGNIFICANT 4 INCH+ STORM EVENTS THAT HAVE OCCURRED RECENTLY, MANY AREAS LIKE THIS FLOOD AND POND FROM STORMWATER ASSOCIATED WITH ROAD DRAINAGE.

IN CONCLUSION, IF YOU HAVE ANY QUESTIONS CONCERNING THIS REPORT, PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

*Joseph R. Theroux*

JOSEPH R. THEROUX  
CERTIFIED SOIL SCIENTIST  
MEMBER SSSSNE, NSCSS, SSSA.